

| | | | | |
|-------------|--|--|---|--|
| PPPL | PRINCETON PLASMA PHYSICS LABORATORY | POLICY | | No. P-036 Rev 1 page 1 of 1 |
| | | Subject: Asbestos Management | Effective Date: June 30, 2004 | Initiated by: M&ES Division Head |
| | Supersedes: TCR P-036, Rev. 0 June 30, 1993 | | Approved: Director | |

It is the policy of PPPL that Asbestos and Asbestos Containing Materials (ACM) which are in good condition shall be left in place and protected from damage as much as practical. Asbestos and ACM shall be removed only when they pose a hazard to human health and/or the environment. In addition, Asbestos and ACM shall be removed in support of renovation and new construction projects.

The Materiel and Environmental Services (M&ES) Division has the responsibility and the authority for managing Asbestos and ACMs at PPPL. This authority has been granted in order to control unsatisfactory work activities, to control further processing, delivery, installation, renovation, demolition, removal, and disposal of ACMs, and to ensure that work is performed in compliance with all state and federal laws and regulations. The responsibilities and tasks surrounding Asbestos projects are defined in procedure EWM-005. Adherence to this policy will ensure PPPL compliance with NESHAP, OSHA, and New Jersey Departments of Health and Labor regulations.

Personnel, either PPPL employees or subcontractors, working in asbestos projects must have completed a 40-hour Worker or Contractor/Supervisor Asbestos training course and annual 8 hour refresher that meet the requirements set forth in 40 CFR 763, "Asbestos Model Accreditation Plan".

PPPL employees and subcontractors shall conduct all activities involving Asbestos and ACM in accordance with this policy.

Reference Documents

OSHA 29 CFR 1910.1001 Asbestos
EWM-005 Asbestos Management Services